

Welding Machine

MIG140 Welder



Accessories :

- 1/ Tweco style Mig Gun (3 meter, approx 10 ft).
- 2/ Ground Clamp w/cable (2.8 meter, approx 9.2 ft).
- 3/ Gas Regulator with Flow Gauge.
- 4/ Gas Hose.
- 5/ Contact Tip (0.030" & 0.035" - @1pc).
- 6/ ER70S-6 Wire – 1 spool of 2lb 0.023" (=0.6mm).
- 7/ User's Manual.

CUT40H Plasma Cutter



Accessories :

- 1/ LT-50 Trafimet style Plasma Torch (5.8 meter, approx 19 ft).
- 2/ Ground Clamp w/cable (2.8 meter, approx 9.2 ft).
- 3/ 1 ft 240V to 110V grounded adapter cable NEMA 50.
- 4/ Tip – 1 pc.
- 5/ Electrode – 1 pc.
- 6/ User's Manual.

Model	Input Power	No-Load Voltage	Output Current	Rated Duty Cycle	Weight (kg)	Dimensions (L)x(W)x(H) (mm)
MIG140	115V 20Amp 60Hz	28V	25-140A	20% @90A	20.6	408 x 244 x 367
CUT40H	110V 33Amp 60Hz	253V	33A	60% @33A	9.7	460 x 225 x 305
	220V 40Amp 60Hz	253V	40A	60% @40A	9.7	460 x 225 x 305

Machine Shell : different colors are available (Red, Blue, Grey)...

GRACEDUTY COMPANY LIMITED

Room 1102 - 1104, 11/F., CRE Centre,
 889 Cheung Sha Wan Road, Kowloon, Hong Kong, China
 Tel: (852) 2420-5808 (6 Lines) Fax: (852) 2420-5507
 E-mail : welding@graceduty.com.hk http://www.graceduty.com.hk

rev.052215